



SCHEMATIC



SERVICE PARTS
C130 SWITCH KIT FOR ONE COMPLETE
FEEDER CONTROL REPAIR
SMALL ON/OFF ROCKER SWITCH



RYAN CONTROL, INC. 2024 N. LINDSTEDT AVE.	
MORTON, ILL. 62451 317-549-3935 BOD 232-1857	
MODEL	E100
CONTROL 1	FEEDER
CONTROL 2	
CONTROL 3	
CONTROL 3/4	
SENSOR	
300/213V ENCLOSURE	M48